

CGC

Serial No.: 10/731,494



PATENT

CERTIFICATE OF MAILING (37 CFR 1.8a)

I hereby certify that this paper (along with any paper referred to as being attached or enclosed) is being deposited with the United States Postal Service on the date shown below with sufficient postage as first class mail in an envelope addressed to: Certificate of Correction Branch, Commissioner for Patents, U.S. Patent and Trademark Office, P.O. Box 1450, Alexandria, VA 22313-1450.

10/4/05
Date

JANET FARR
Name of person mailing paper

Janet Farr
Signature

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: Halliyal et al.

Serial No.: 10/731,494 Patent No.: 6,949,481

Filed: Dec. 9, 2003 Issue Date: Sep. 27, 2005

Title: IMPROVED PROCESS FOR FABRICATION OF SPACER LAYER
WITH REDUCED HYDROGEN CONTENT IN SEMICONDUCTOR
DEVICE

Examiner: W. David Coleman

Certificate

Docket No.: AMDS.PAF01194US

OCT 11 2005

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
(FOR PTO MISTAKE UNDER 37 C.F.R. § 1.322(a))

Certificate of Correction Branch
Commissioner for Patents
U.S. Patent and Trademark Office
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

Request is made for issuance of a certificate of correction to correct Office mistakes in the printing of the subject patent. Enclosed in duplicate is completed form PTO/SB/44 showing the correction(s) to be made.

OCT 17 2005

Serial No.: 10/731,494

To expedite issuance of the certificate of correction, the following table identifies where in the record the correct language can be found.

Location of Error	Location of Correct Language
Column 6, line 29	Page 8, line 12
Claim 19, line 2	Page 25, line 22

Upon issuance, please send the Certificate to:

Renner, Otto, Boisselle & Sklar, LLP
1621 Euclid Avenue
19th Floor
Cleveland, Ohio 44115

No fee is believed to be necessary, but if there are any fees resulting from this communication, please charge same to our Deposit Account No. 18-0988, our Order No. AMDS.PAF01194US.

Respectfully submitted,

RENNER, OTTO, BOISSELLE & SKLAR, LLP

By 
Thomas W. Adams, Reg. No. 35,047

1621 Euclid Avenue
Nineteenth Floor
Cleveland, Ohio 44115
Telephone: (216) 621-1113
Facsimile: (216) 621-6165

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**Page 1 of 1

PATENT NO. : 6,949,481

APPLICATION NO.: 10/731,494

ISSUE DATE : Sep. 27, 2005

INVENTOR(S) : Halliyal et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 29, replace "insulator (SOD) semiconductor" with --insulator (SOI) semiconductor--.
Claim 19, line 2, replace "about 0-1 atomic" with --about 0.1 atomic--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Renner, Otto, Boisselle & Sklar LLP
1621 Euclid Ave. - 19th Floor
Cleveland, Ohio 44115

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

Oct 17 2005
Oct 17 2005

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**Page 1 of 1

PATENT NO. : 6,949,481

APPLICATION NO.: 10/731,494

ISSUE DATE : Sep. 27, 2005

INVENTOR(S) : Halliyal et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 29, replace "insulator (SOD) semiconductor" with --insulator (SOI) semiconductor--.
Claim 19, line 2, replace "about 0-1 atomic" with --about 0.1 atomic--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Renner, Otto, Boisselle & Sklar LLP
1621 Euclid Ave. - 19th Floor
Cleveland, Ohio 44115

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

OCT 17 2005